


# CORNER RECORD

Document Number 99-178

City of RIVERSIDE County of RIVERSIDE, California

Brief Legal Description Portion of Lot 14, Block 17, M.B. 1/70 S.B.Co. lying in the N.E. 1/4 of Sec. 4, T.3 S., R. 5 W. S.B.M.  
(Include: Sec., Twp., Rge., and Meridian or Rancho)



## CORNER TYPE

- |  |  |
|--|--|
| <input type="checkbox"/> Government Corner                   | <input type="checkbox"/> Control             |
| <input type="checkbox"/> Meander                             | <input checked="" type="checkbox"/> Property |
| <input type="checkbox"/> Rancho                              | <input type="checkbox"/> Other               |
| <input type="checkbox"/> Date of Survey <u>FEB. 19, 1999</u> |  |

## COORDINATES (OPTIONAL)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner - ☐ Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found rear corners. Street centerline and Right-of-Way monumentation and adjoining Lot corners per R.S. 6/41 to reset  
Corner by proration.

A description of the physical condition of the monument as found and as set or reset:

See Page 2 of 2

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the  
Land Surveyor's Act on MAY 3, 19 99.

Signed Joseph N. Beeler L.S. Number 4055

## COUNTY SURVEYOR'S STATEMENT


This Corner Record was received June 25, 19 99.

And examined and filed June 29, 19 99.

Signed Michael C. Parks Title Senior Land Surveyor

County Surveyor's Comment \_\_\_\_\_

THE FILING OF THIS CORNER RECORD  
DOES NOT RELIEVE THE SURVEYOR  
FROM ANY RESPONSIBILITY OF THE  
FILING OF A RECORD OF SURVEY



99-195